

Labor and Material Report 4-15-1931

Building 144 Sherman
~~Vacant lot~~
~~no measurement~~
 ?

● Curb Box

6 Main Elev. of Main at tap 5

Gate at ● Gate at ●

● Curb Box

Sherman St. 144
 Ave. No. 144

Name of Owner Charles Dunn

Measured in 1962

Labor and Mat'l. Report 1931

● Curb Box

6 Main Elev. of Main at tap 5

Gate at ● Gate at ●

14' to main
3/4" copper

Was Vacant lot. ● Curb Box
 since 1931.
 New House 1962

2-Taps in This Lot.

TAX ID# 309.7-4-7

LSM-8C-3-10-61

Labor and Materials

1	Copper Lead	Connection	3/4	\$ 2.60
1	Curb	Cock Valve T.S. & V.	in.	\$ 2.27
1	Service Box Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2	Buff. or Rdway	\$ 1.38
14	Ft.	Copper Galv. Iron Cast Iron	Pipe at	\$ 2.52
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt	at	\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
1 1/2	Hrs. Foreman	at		\$.31
1 1/4	Hrs. Common Labor	at		\$.63
8	Hrs. Common Labor	at		\$ 3.60
	Hrs. Mason	at		\$
	Hrs. Mason's Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.			\$ 14
	Trucking			\$ 1-
	Builders' Use of Water			\$
Total \$				14.45

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4	\$
1	Curb	Cock Valve T.S. & V.	3/4 in.	\$
1	Service box Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2	Buff. or Rdway	\$
14	Ft.	Copper G.I. C.I.	3/4 in. Pipe at	\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Coupl'gs	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man	—1 at		\$
	Hrs. Water Maint. Man	—2 at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.	at \$ per C		\$
	Trucking			\$
	Pav't Patch			\$
	O'head			\$