

21-55

Labor and Material Report 4-15 19 31

Fielding 146 Sherman
Vacant lot
No Measurements
 ?

● Curb Box

6 Main Elev of Main at tap 5

Gate at ● Gate at ●

● Curb Box

Sherman ~~St.~~ ~~Pl.~~ Ave. No. 146

Name of Owner George J. Hoffis.

Measured in Dec. 29 - 1965,

Labor and Mat'l. Report

TAX ID # 309.7.4-8

6" Main Elev. of Main at tap 5"

Gate at ● Gate at ●

14' to MAIN
3/4" COPPER

● Curb Box

2 Taps in this lot.
New House 1964-5.
Was Vacant lot since
1931.

LSM-5C-3-10-61

Labor and Materials

1	Copper Lead	Connection	3/4"	\$ 2.60
1	Curb	Cock Valve T.S. & V.	in.	\$ 2.27
1	Service Box	Short 3 1/2 x 4 1/2		\$ 1.38
	Old returned	Long 4 1/2 x 5 1/2	Buff or Rdway	
14	Ft.	Copper Galv. Iron Cast Iron	Pipe at	\$ 2.52
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt	at	\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
1/2	Hrs. Foreman	at		\$ 31
1 1/4	Hrs. Common Labor	at Tapper		\$ 63
8	Hrs. Common Labor	at		\$ 2.60
	Hrs. Mason	at		\$
	Hrs. Mason's Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.			\$.14
	Trucking			\$ 1-
	Builders' Use of Water			\$
Total \$				14.45

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4"	\$
1	Curb	Cock Valve T.S. & V.	3/4 in.	\$
1	Service box	Short 3 1/2 x 4 1/2		\$
	Old returned	Long 4 1/2 x 5 1/2	Buff or Rdway	
14	Ft.	Copper G.I. G.I.	Pipe at	\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Coupl'gs	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man	1 at		\$
	Hrs. Water Maint. Man	2 at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.	at \$ per C		\$
	Trucking			\$
	Pay't Patch			\$
				\$
				\$
				\$
	O'head			\$
				\$