

Labor and Materials

1	Copper	Connection	3/4	\$	2.60
1	Lead			\$	
1	Curb	Cock Valve T.S. & V.	in.	\$	2.27
1	Service Box	Short 3/4x4 1/2		\$	1.38
	Old returned	Long 4 1/2x3 1/2		\$	
		Buff. or Rdway		\$	
14	Ft.	Copper Galv. Iron	Pipe at	\$	2.52
		Cast Iron		\$	
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	Couplings to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lbs. Br. Stone	at		\$	
	Lbs. Sand	at		\$	
	Bags Cement	at		\$	
	Paving Brick	Mack Red Asphalt	at	\$	
	Lead Joints	at		\$	
	Leadite Joints	at		\$	
1.2	Hrs. Foreman	at		\$	31
1.14	Hrs. Common Labor	Tapper		\$	63
3	Hrs. Common Labor	at		\$	3.60
	Hrs. Mason	at		\$	
	Hrs. Mason's Helper	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins.			\$	14
	Trucking			\$	1-
	Builders' Use of Water			\$	
	Total			\$	14.45

31-58 Labor and Material Report 4-13-19 31

Building 152 Sherman
Vacant lot
no measurements

● Curb Box

6 Main

Elev of Main at tap 5

Gate at ●

● Gate at

● Curb Box

14' to main
3/4" copper