

Labor and Materials

1	Copper	Connection	3/4"	\$ 2.60
1	Curb	Cock Valve		\$ 2.27
1	Service Box	Short 3/4x1 1/2		\$ 1.38
	Old returned	Long 1 1/2x5 1/2		
		Buff. of Rdway		
14	Pt.	Copper Galv. Iron	Pipe at	\$ 2.52
		Cast Iron		
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt	at	\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
1/2	Hrs. Foreman	at		\$ 31
1 1/4	Hrs. Common Labor	Tapper		\$ 63
8	Hrs. Common Labor	at		\$ 3.60
	Hrs. Mason	at		\$
	Hrs. Mason's Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.			\$ 14
	Trucking			\$ 1
	Builders' Use of Water			\$
Total \$				14 45

31-59 Labor and Material Report 4-17-1931

Lot 154 Fielding
Sherman Ave.

No Measurements

Curb Box

6 Main

Elev of Main at tap 5

Gate at

Gate at

Curb Box

14' to main

3/4" copper