

LABOR AND MATERIALS

Copper	}	Connection	\$	
Lead				
Curb	}	Cock	in.	\$
		Valve		
		T. S. & V.		
Service box	}	Short 3½ x 4½	}	\$
		Long 4½ x 5½		
Old returned				
8'8" Ft.	}	Copper	}	\$
¾ in.		G.I.		
		C.I.		
		Pipe at		
Nipples		in. at		\$
Bushings		to in. at		\$
Red'g	}	Coupl'gs	to in. at	\$
Union		in. at		\$
Meter		in. at		\$
				\$
Compound Joints		at		\$
Maintenance Foreman				\$
Hrs. Water Maint. Man-1		at		\$
Hrs. Water Maint. Man-2		at		\$
Hrs. Garage Foreman		at		\$
Hrs. Labor		at		\$
Hrs. Compressor		at		\$
				\$
Trucking				\$
Pav't Patch				\$
				\$
				\$
				\$
				\$

~~St.~~
~~Pt.~~
 Ave. No. 22

Sherman

Name of Owner Edmund Spawick

Labor and Mat'l. Report 9 1986

Sherman Ave.

Main

Elev. of
Main at tap

Gate at •

• Gate at

• Curb Box

8'8" to main

¾" copper

LSM-5C-6-1-67