

LABOR AND MATERIALS

Copper	} Connection	-----	\$
Lead		-----	\$
Curb	} Cock Valve T. S. & V.	----- in.	\$
Service Box		-----	\$
Old returned	} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway	-----	\$
		-----	\$
		-----	\$
Ft. ----- in.	} Copper Galv Iron Cast Iron	Pipe at -----	\$
Nipples ----- in. at -----		-----	\$
Bushings ----- to ----- in. at -----		-----	\$
Red'g Inc'g	} Couplings	----- to ----- in. at -----	\$
Union ----- in. at -----		-----	\$
Meter ----- in. at -----	-----	\$	
Lead Joints at -----	-----	\$	
Leadite Joints at -----	-----	\$	
Hrs. Foreman at -----	-----	\$	
Hrs. Chauffeur at -----	-----	\$	
Hrs. Tapper at -----	-----	\$	
Hrs. Labor at -----	-----	\$	
Hrs. Labor at -----	-----	\$	
Hrs. Compressor at -----	-----	\$	
Compensation Ins. -----	-----	\$	
Trucking -----	-----	\$	
Builders Use of Water -----	-----	\$	
-----	-----	\$	
-----	-----	\$	
-----	-----	\$	
-----	-----	\$	

St
Pt

Sherman Ave. No. 28

Name of Owner
RENEWAL TAP - Nov 2001

Labor and Mat'l. Report 19 14

Main Elev. of Main at tap

Gate at ● ● Gate at

TAX ID # 302.20-20-6

● Curb Box