

Labor and Materials

1	Lead Connection	3/4	\$
1	Curb Cock	1" <i>Water</i>	\$
1	Service Box	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buffalo	\$
19	Ft. 1" in. G. I. Pipe at		\$
1	Nipples	3/4 in. at	\$
	Bushings	in. at	\$
1	Red'g Coup	1" to 3/4 in. at	\$
	Inc'g Coup	to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Cu. Yds. Br. Stone at		\$
	Cu. Yds. Sand at		\$
	Bags Cement at		\$
	Pav. Brick	{ Mack Red Asphalt } at	\$
6	Hrs. Foreman at		\$
2.0	Hrs. Com. Labor at		\$
	Hrs. Mason at		\$
	Hrs.	at	\$
	Hrs.	at	\$
90	Builders' Use of Water		\$
	Truck	1.00	\$
		at	\$
		at	\$
		at	\$
		at	\$
	Total	\$	17.94

Labor and Material Report Dec 19 1922

Renewal 3/4" tap at 29' show



Curb Box

6 Main Elev. of Main at tap 4 1/2

Gate at Gate at

TAX ID# 302.20.14-22

Curb Box

1" inspection  
19' to main  
1" G.I.