

Labor and Material Report

June 16 1935

63 Sherman Ave.

● Curb Box

6" Main

Elev. of Main at tap

Gate at ●

● Gate at

● Curb Box

Labor and Material Report

June 19 1935

M Dolens lot.

M DOLENS HOUSE
#61

35' 0"
40' 8"
● Curb Box

6" Main Sherman Ave

Elev. of Main at tap

5'

Gate at ●

● Gate at

● Curb Box

20' to main
3/4" Gap.

Labor and Materials

<i>cap.</i>	Lead Connection	\$	
1	Curb Cock	\$	
1	Service Box (Short 3 1/2 x 4 1/2) Old returned (Long 4 1/2 x 5 1/2) <i>Buffalo</i>	\$	
<i>28</i>	<i>3 1/2</i> Ft. in. Gal. Pipe at	\$	
	Nipples in. at	\$	
	Bushings to in. at	\$	
	Red'g Coup. to in. at	\$	
	Inc'g Coup. to in. at	\$	
	Union in. at	\$	
	Meter in. at	\$	
	Cu. Yds. Br. Stone at	\$	
	Cu. Yds. Sand at	\$	
	Bags Cement at	\$	
	Paving Brick (Mack Red Asphalt) at	\$	
<i>3</i>	Hrs. Foreman at	\$	
<i>13</i>	Hrs. Common Labor at	\$	
	Hrs. Mason at	\$	
	Hrs. at	\$	
	Hrs. at	\$	
<i>no.</i>	Builders' Use of Water	\$	
	at	\$	
	at	\$	
	at	\$	
	at	\$	
	Total	\$	

Labor and Materials

	Copper Lead } Connection 1"	\$	<i>3.22</i>
1	Curb { Cock Valve } 2" in.	\$	<i>7.50</i>
1	Service Box (Short 3 1/2 x 4 1/2) Old returned (Long 4 1/2 x 5 1/2) <i>Buff. or Redway</i>	\$	<i>2.63</i>
<i>2.0</i>	Ft. 2" in. { Copper Galv. Iron Cast Iron } Pipe at	\$	<i>6.67</i>
1	Nipples 1/4 in. at	\$	<i>25</i>
1	Bushings 1/4 to 3/4 in. at	\$	<i>15</i>
1	Red'g Inc'g } Couplings 1/4 to 1/2 in. at	\$	<i>35</i>
1	Union 5/8 in. at	\$	<i>80</i>
	Meter in. at	\$	
	Lbs. Br. Stone at	\$	
	Lbs. Sand at	\$	
	Bags Cement at	\$	
	Paving Brick (Mack Red Asphalt) at	\$	
	Lead Joints at	\$	
	Leadite Joints at	\$	
<i>4</i>	Hrs. Foreman at	\$	<i>2.50</i>
<i>14</i>	Hrs. Common Labor at	\$	<i>57.69</i>
	Hrs. Common Labor at	\$	
	Hrs. Mason at	\$	
	Hrs. Mason's Helper at	\$	
	Hrs. Compressor at	\$	
	Compensation Ins.	\$	<i>31</i>
	Trucking	\$	<i>1.50</i>
<i>no.</i>	Builders' Use of Water	\$	
	Total	\$	<i>294.7</i>