

### LABOR AND MATERIALS

1	Copper <del>Lead</del>	} Connection	3/4		\$ 280
1	Curb	} Clock Valve T. S. & V.	3/4	in.	\$ 3.60
1	Service box Old returned	} Short 3 1/2 X 4 1/2 Long 4 1/2 X 5 1/2 Buff or Rdway			\$ 590
19 Ft.	3/4 in.	} Copper Galv. Iron Cast Iron		Pipe at	\$ 35
	Nipples			in. at	\$
	Bushings			to in. at	\$
	Red'g Inc'g	} Couplings		to in. at	\$
	Union			in. at	\$
	Meter			in. at	\$
	Lead Joints			at	\$
	Compound Joints			at	\$
	Hrs. Foreman			at	\$
	Hrs. Chauffeur			at	\$
	Hrs. Tapper			at	\$
	Hrs. Labor			at	\$
	Hrs. Labor			at	\$
	Hrs. Compressor			at	\$
	Compensation Ins.				\$
	Trucking				\$
	Builders Use of Water				\$
	<i>Tap by Miller</i>				\$
					\$
					\$
					\$
					\$
					\$

St. ✓  
 Pl.  
 Ave. No. 14

Summer

Name of Owner Fred Hammond

---

Labor and Mat'l. Report July 30 1947

6 Main Elev. of Main at tap 5'6

Gate at ● ● Gate at

● Curb Box

19' to main

3/4" copper

LSM-SC-6-1-45