

LABOR AND MATERIALS

1	Copper	} Connection	3/4"	\$	
1	Lead				
1	Curb	} 3/4" old style.	in.	\$	
	Cock				
	Valve				
		T.S. & V.			
1	Service box	} { Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway }		\$	
	Old returned				
7	Ft. 3/4 in.	} Pipe at		\$	
					Copper
					G.I.
		G.I.			
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g	} Coupl'gs	to in. at	\$	
	Inc'g				
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Compound Joints	at		\$	
	Maintenance Foreman			\$	
	Hrs. Water Maint. Man-1	at		\$	
	Hrs. Water Maint. Man-2	at		\$	
	Hrs. Garage Foreman	at		\$	
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins. at \$	per C		\$	
	Trucking			\$	
	Pav't Patch			\$	
	Tap made 7-23-25			\$	
				\$	
				\$	
	O'head			\$	
				\$	

St. \_\_\_\_\_  
Pl. \_\_\_\_\_  
Ave. No. 86

Sherman

Name of Owner  
Robert Jones

Labor and Mat'l. Report July 23 1925

Morton Ave

garage

64' 4"

47' 8"

74' 3"

● Curb Box

Sherman Ave

TAX ID # 309.7-7-6

6" Main

Elev. of Main at tap 5'

Gate at ●

7' to main

3/4" copper

● Curb Box

House Built in 1966.

Copy

LSM-5C-3-10-61