

LABOR AND MATERIALS

Copper	{	Connection	\$
Lead			
Curb	{	Cock Valve	\$
		T. S. & V.	in. \$
Service box	{	Short 3½x4½	
Old returned		Long 4½x5½	\$
		Buff or Rdway	
Ft.	{	Copper	\$
in.		G. I.	Pipe at \$
		C. I.	
Nipples	in. at		\$
Bushings	to	in. at	\$
Red'g	{	Coupl'gs	to in. at \$
Inc'g			
Union	in. at		\$
Meter	in. at		\$
Lead Joints	at		\$
Compound Joints	at		\$
Hrs. Water Maint. Man	—1 at		\$
Hrs. Water Maint. Man	—2 at		\$
Hrs. Labor	— at		\$
Hrs. Labor	— at		\$
Hrs. Compressor	at		\$
Compensation Ins.	at \$	per C.	\$
Trucking			\$
Pav't Patch			\$
			\$
			\$
			\$
O'head			\$

Between
St. 88+108
Ave. No.

SHERMAN

Name of Owner Calvary Tabernacle
Methodist Church

Measured IN 12-14-51

Labor and Mat'l. Report 19

#88
TAX ID # 309.7-7-7 Elev. of Main at tap

Gate at ● ● Gate at

● Curb Box

● Curb Box

July 15
 Labor and Material Report 1923

87 Sherman Ave

House 88
 Sherman Ave

70'9" 82'3" Curb Box

Main Elev. of Main at tap

Gate at 28' to main 3/4" copper Gate at

Curb Box

28'

87 Sherman Ave

Sept 22
 Labor and Material Report 1924

48 Sherman Ave

Tuy 28'10" Curb Box Tuy 27'8" 2

6 Main Elev. of Main at tap 4 1/2

Gate at 5' to main 3/4" copper Gate at

Curb Box

Renewed 4-7-87.

