

Labor and Materials

1	Copper	Connection	\$ 2.60
1	Lead	Connection	\$ 2.27
1	Curb	Cock Valve T.S. & V. in.	\$ 1.28
1	Service Box	Short 3/4x1 1/2	\$ 4.32
	Old returned	Long 1 1/2x3 3/4	
		Build. or Redway	
24	Pt.	Copper Galv. Iron Cast Iron Pipe at	\$
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g Inc'g	Couplings to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone	at	\$
	Lbs. Sand	at	\$
	Bags Cement	at	\$
	Paving Brick	Mack Red Asphalt at	\$
	Lead Joints	at	\$
	Leadite Joints	at	\$
3/4	Hrs. Foreman	at	\$ 47
2	Hrs. Common Labor	at	\$ 7.20
16	Hrs. Common Labor	at	\$
	Hrs. Mason	at	\$
	Hrs. Mason's Helper	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins		\$ .26
	Trucking		\$ 1-
	Builders' Use of Water		\$
Total			\$ 70.50

Labor and Material Report

4-21-1931

131 Sherman Ave

No Measurement

Curb Box

6 Main Elev of Main at tap 5 Gate at

Curb Box

24' to main