

**Labor and Materials**

1	Copper	Connection	\$ 2.60
	Lead		
1	Curb	Cock Valve T. S. & V. in.	\$ 2.27
1	Service Box	Short 3/4x4 1/2	\$ 1.38
	Old returned	Long 4x5 1/2 Buff. or Rdway	
24	Ft.	Copper Galv. Iron Pipe at Cast Iron	\$ 4.32
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g Inc'g	Couplings to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone	at	\$
	Lbs. Sand	at	\$
	Bags Cement	at	\$
	Paving Brick	Mack Red Asphalt at	\$
	Lead Joints	at	\$
	Leadite Joints	at	\$
3/4	Hrs. Foreman	at	\$ 47
7	Hrs. Common Labor	at Tapper	\$ 1.70
16	Hrs. Common Labor	at	\$ 7.20
	Hrs. Mason	at	\$
	Hrs. Mason's Helper	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins.		\$ .26
	Trucking		\$ 1.00
	Builders' Use of Water		\$
Total			\$ 20.50

Labor and Material Report

4-21-1931

133 Sherman Ave

No Measurement

● Curb Box

6 Main

Elev of Main at tap 5

Gate at ●

● Gate at

● Curb Box

24' to main  
3/4" copper