

### Labor and Materials

1	Copper	Connection	\$ 2.70
	Lead		
1	Curb	Cock Valve T-S & V. in.	\$ 2.27
	Service Box	Short 3 1/2 x 4 1/2	
	Old returned	Long 4 1/2 x 5 1/2	\$ 1.38
		Buff. or Rd. way	
24	Pt.	Copper	
		Cast Iron Pipe at	\$ 4.32
		Cast Iron	
	Nipples	in. at.	\$
	Bushings	to in. at.	\$
	Red'g Inc'g	Couplings to in. at.	\$
	Union	in. at.	\$
	Meter	in. at.	\$
	Lbs. Br. Stone	at.	\$
	Lbs. Sand	at.	\$
	Bags Cement	at.	\$
	Paving Brick	Mack Red Asphalt at.	\$
	Lead Joints	at.	\$
	Leadite Joints	at.	\$
3 1/4	Hrs. Foreman	at.	\$ 4.75
2	Hrs. Common Labor	Tapper	\$ 1.00
16	Hrs. Common Labor	at.	\$ 7.20
	Hrs. Mason	at.	\$
	Hrs. Mason's Helper	at.	\$
	Hrs. Compressor	at.	\$
	Compensation Ins.		\$ .26
	Trucking		\$ 1.00
	Builders' Use of Water		\$
Total			\$ 70.50

31-48

Labor and Material Report 4-21-1931

135 *Shannon Ave*

24'

23'-3"

Curb Box

---

6 Main

Elev of Main at tap 5

Gate at ●

● Gate at

---

● Curb Box

24' to main  
copper