

LABOR AND MATERIALS

1 Copper Lead	Connection	1/2	\$ 0.19
1 Curb	Cock Valve T. S. & V.	1/2 in.	\$ 2.10
1 Service Box	Old returned	Short 3/2x4 1/2	\$ 1.50
		Long 4 1/2x5 1/2	
36 Ft.		1/2 in. Pipe at	\$ 3.96
		Copper Galv Iron Cast Iron	
Nipples	in. at		\$
Bushings	to in. at		\$
Red'g Inc'g	Couplings	to in. at	\$
Union	in. at		\$
Meter	in. at		\$
Lead Joints	at		\$
Leadite Joints	at		\$
Hrs. Foreman	at		\$
8 Hrs. Chauffeur	at	6x1/2	\$ 5.00
Hrs. Tapper	at		\$
Hrs. Labor	at		\$
Hrs. Labor	at		\$
Hrs. Compressor	at		\$.16
Compensation Ins.			\$ 2.00
Trucking			\$
Builders Use of Water			\$
Tape by Miller			
Fillings on Robinson			
Bill			
			\$

15.44

St.

Pl.

Sewer Proposal Ave. No. _____

Name of Owner (For Pressure Gauge)

City of Glens Falls

Labor and Mat'l. Report June 15 1929

● Curb Box

7 Main

Elev. of Main at tap 6

Gate at ●

● Gate at

● Curb Box

No measurements,

New York