

LABOR AND MATERIALS

1	Copper Lead	{ Connection	3/4	\$
1	Curb	{ Cock Valve T. S. & V.	3/4 in.	\$
1	Service Box Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway		\$
4	Ft.	3/4 in.	{ Copper Galv Iron Cast Iron	Pipe at \$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	{ Couplings	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
	Hrs. Foreman	at		\$
✓	Hrs. Chauffeur	at	6 1/2	\$ 125
	Hrs. Tapper	at		\$
✓	Hrs. Labor	at	45	\$ 90
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.			\$
	Trucking			\$
	Builders Use of Water			\$
	<i>Tap by Penon</i>			\$
				\$
				\$
				\$
				\$

St. V

Pl.

Sherman Town Ave. No. _____

Name of Owner *Disposal Plant*

City of Glen Falls

Labor and Mat'l. Report *June 21 1939*

● Curb Box

4 Main Elev. of Main at tap *6*

Gate at ● ● Gate at

● Curb Box

No measurements

New Tap to be changed