

### LABOR AND MATERIALS

1	Copper Lead	} Connection	3/4		\$ 280
1	Curb	{ Clock Valve F. S. & V. }	3/4	in.	\$ 360
1	Service box Old returned	{ Short 3/4 X 4/4 Long 4/4 X 5/4 Buff or Rdway }			\$ —
21	Ft.	{ Copper Galv. Iron Cast Iron }	3/4	in.	Pipe at \$ 735
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	Couplings	to	in. at	\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints	at			\$
	Compound Joints	at			\$
2	Hrs. Foreman at	WMM	1.01	\$ 2.02	0
8	Hrs. Chauffeur at		91	\$ 7.28	9
	Hrs. Tapper at			\$	
7	Hrs. Labor at		80	\$ 5.60	4
	Hrs. Labor at			\$	
	Hrs. Compressor at			\$	
	Compensation Ins.			\$ 33	
	Trucking			\$ 1	
	Builders Use of Water			\$	
	Tap by Walsms/c				\$
					\$
					\$
					\$
					\$
					\$ 29.98

St. \_\_\_\_\_  
 Pl. \_\_\_\_\_  
 Ave. No. 17

Shippy

Name of Owner Starbuck

---

Labor and Mat'l. Report July 9 1947

24'8"      16'10"

● Curb Box

---

6 Main      Elev. of Main at tap 5

Gate at ●      ● Gate at

---

21' to main  
3/4" Copper

● Curb Box

TAX ID # 302.19-22-16

LSM-5C-6-1-45