

LABOR AND MATERIALS

1. Copper	Connection	3/4	\$	2.87	
1. Lead					
1. Curb	Cock Valve	3/4 in.	\$	3.62	
	T. S. & V.				
1. Service box	Short 3 1/2 X 4 1/2	} same —	\$		
Old returned	Long 4 1/2 X 5 1/2				
	Buff or Rdway				
13. Ft.	3/4 in.	Copper	Pipe at	32	\$ 4.16
		G.I.			
		G.I.			
Nipples	in. at		\$		
Bushings	to in. at		\$		
Red'g					
Inc'g	Coupl'gs to in. at		\$		
Union	in. at		\$		
Meter	in. at		\$		
Lead Joints	at		\$		
Compound Joints	at		\$		
Hrs. Water Maint. Man—1	at		\$		
Hrs. Water Maint. Man—2	at		\$		
Hrs. Labor—	at		\$		
Hrs. Labor—	at		\$		
Hrs. Compressor	at		\$		
Compensation Ins. at \$	per C.		\$		
Trucking			\$		
Pav't Patch			\$		
<i>Tap by M. J. ...</i>					
O'head			\$		
				\$10.65	

St.
Pl. Ave. No. 20

Shippy

Name of Owner

Smith

Labor and Mat'l. Report

June 17 1949



6 Main

Elev. of Main at tap 5

Gate at ●

● Gate at

13' to main
3/4" COPPER

● Curb Box

TAX ID # 302.19-25-11

Tube Charge to Shippy St
Est