

LABOR AND MATERIALS

1	Copper	Connection	3/4"		\$ 2.76
	Lead				
1	Curb	Cock Valve	3/4 in.		\$ 3.49
		T. S. & V.			
1	Service box	Short 3 1/2 X 4 1/2			4.74
	Old returned	Long 4 1/2 X 5 1/2			
		Buff or Rdway			
11	Ft.	Copper	3/4 in.	Pipe at 35	\$ 3.95
		G.I.			
		G.I.			
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g				\$
	Inc'g	Coupl'gs to in. at			\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints	at			\$
	Compound Joints	at			\$
	Hrs. Water Maint. Man-1	at			\$
1 1/2	Hrs. Water Maint. Man-2	at	1.24		\$ 1.86
1 1/2	Hrs. Labor	at	1.13		\$ 1.69
	Hrs. Labor	at			\$
	Hrs. Compressor	at			\$
	Compensation Ins.	at \$3.706 per C			\$ 13
	Trucking				\$ 1.00
	Pav't Patch	Refer Pav'g			\$
	Tap by Gissard				\$
	7-21-52				\$
	O'head				\$
					\$ 19.52

41
 St. Shippey
~~Pl.~~
 Ave. No. 29

Name of Owner Gleason

Labor and Mat'l. Report July 21 1952

29 41

31'3" 37'9"

● Curb Box

6" Main
Elev. of Main at tap 4 1/2'

Gate at ●
● Gate at

11' to main
3/4" copper

● Curb Box

TAX ID# 302.19-15-28

LSM-5C 5 15-48