

19

Labor and Materials

Copper } Connection.....		\$ 3.20
Lead }		
Curb { Cock }		\$ 1.00
Valve }		
T. S. & V. }		
Service Box { Short 3 1/2 x 4 1/2 }		\$ 1.30
Old returned { Long 4 1/2 x 5 1/2 }		
	{ Buff. or Rdway }	
1/2 Ft. in. { Copper } Pipe at.....		\$ 2.64
	{ Galv. Iron }	
	{ Cast Iron }	
Nipples..... in. at.....		\$
Bushings..... to..... in. at.....		\$
Red'g } Couplings..... to..... in. at.....		\$
Inc'g }		
Union..... in. at.....		\$
Meter..... in. at.....		\$
Lbs. Br. Stone at.....		\$
Lbs. Sand at.....		\$
Bags Cement at.....		\$
Paving Brick { Mack } at.....		\$
	{ Red }	
	{ Asphalt }	
Lead Joints at.....		\$
Leadite Joints at.....		\$
1 Hrs. Foreman at.....	6 1/2	\$ 63
7 Hrs. Common Labor at.....	50	\$ 3.50
6 Hrs. Common Labor at.....	20 1/2	\$ 2.44
Hrs. Mason at.....		\$
Hrs. Mason's Helper at.....		\$
Hrs. Compressor at.....		\$
Compensation Ins.....		\$ 1.00
Trucking.....		\$ 1.7
Builders' Use of Water.....		\$
Total \$		158.8

28-49 19

Labor and Material Report 19

TAX ID # 302.16-6-19

Main Elev. of Main at tap 5'

Gate at ● 12' to main ● Gate at

3/4" COPPER

● Curb Box

Old gate photo