

Labor and Materials		
1	Lead Connection	34
1	Curb Cock	34
1	Service Box	Short 81 x 4
	Old returned	Long 41 x 51
		Buffalo
7	Ft. in. G.I. Pipe at	Box Top, CAP
	Nipples	in. at
1	Bushings	1/2 to 3/4 in. at
	Red'g Coup	to in. at
	Inc'g Coup	to in. at
	Union	in. at
	Meter	in. at
800	Cu. Yds. Br. Stone at	
600	Cu. Yds. Sand at	
2	Bags Cement at	
90	Paving Brick	{ Mack Red Asphalt } at
1	Hrs. Foreman at	
14	Hrs. Common Labor at	
4	Hrs. Mason at	
4	Hrs. Helper at	
	Hrs.	at
	Builders' Use of Water	at
	Compressor	at
	Truck	at
		at
	Total	\$ 30.58

Labor and Material Report *Sub 4 1926*

6-8 SOUTH ST  
6-8 SOUTH

10 Main

Elev. of Main at tap 6

Gate at ● Gate at ●

● Curb Box

This Place Razed.  
Shut off at Curb.  
Dec. 18-61  
Near Light Pole Curb Stop  
Under Concrete Walk