

LABOR AND MATERIALS

1	Copper	{ Connection	$\frac{3}{4}$	\$	2.29
1	Lead				
1	Curb	{ Cock Valve	$\frac{3}{4}$ in.	\$	2.70
		{ T. S. & V.			
1	Service box	{ Short $3\frac{1}{2} \times 4\frac{1}{2}$		\$	4.25
	Old returned	{ Long $4\frac{1}{2} \times 5\frac{1}{2}$			
		{ Buff or Rdway			
22	Ft.	{ Copper		\$	7.70
	$\frac{3}{4}$ in.	{ G. I.	Pipe at 35		
		{ C. I.			
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g	{ Coupl'gs	to in. at	\$	
	Inc'g				
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Compound Joints	at		\$	
	Hrs. Water Maint. Man-1	at		\$	
9	Hrs. Water Maint. Man-2	at 1.02		\$	9.18
14	Hrs. Labor	at 91		\$	12.74
	Hrs. Labor	at		\$	
1	Hrs. Compressor	at		\$	
	Compensation Ins. at \$	per C.		\$	4.9
	Trucking			\$	1.10
	Pav't Patch			\$	8.10
	Tap 4" Main			\$	
	O'head			\$	
				\$	48.45

35-1752

South

St. Pl. Ave. No. 201

Name of Owner
Thomas

Labor and Mat'l. Report *June 2* 19*50*

25'7" 27'3"

● Curb Box

6 Main Elev. of Main at tap 5

Gate at ● ● Gate at

22' to main
3/4" copper

● Curb Box

Tap on Fourth St,
TAX ID # 309.12-14-5

LSM-5C 10-21-49