

### Labor and Materials

Copper	} Connection.....	\$.....	
Lead			
Curb	} Cock Valve T. S. & V. }	..... in ..... \$.....	
Service Box		} Short 3½ x 4½ Long 4½ x 5½ Buff. or Rdway }	..... \$.....
Old returned			
Ft. .... in.	} Copper Galv Iron Cast Iron }	Pipe at ..... \$.....	
Nipples		..... in. at ..... \$.....	
Bushings		..... to ..... in. at ..... \$.....	
Red'g Inc'g	} Conplings.....	..... to ..... in. at ..... \$.....	
Union		..... in. at ..... \$.....	
Meter	..... in. at ..... \$.....		
Lead Joints	at ..... \$.....		
Leadite Joints	at ..... \$.....		
Hrs. Foreman	at ..... \$.....		
Hrs. Chauffeur	at ..... \$.....		
Hrs. Tapper	at ..... \$.....		
Hrs. Labor	at ..... \$.....		
Hrs. Labor	at ..... \$.....		
Hrs. Compressor	at ..... \$.....		
Compensation Ins.	..... \$.....		
Trucking	..... \$.....		
Builders Use of Water	..... \$.....		
	..... \$.....		
	..... \$.....		
	..... \$.....		
	..... \$.....		
	..... \$.....		
	..... \$.....		

South St. Pl. Ave. No. 33

Name of Owner A+P Store

Labor and Mat'l. Report Apr 6 1943

Hand Wagon

A+P Store

13'9" 6'6"

● Curb Box

Main Elev. of Main at tap

Gate at ● Gate at

● Curb Box

This Tap shut off at Main.

#25-#33 TAX ID# 302.20-27-2

City of GF