

Labor and Materials

1	Copper	Connection	3/4	\$ 2.60
1	Curb	Cock Valve	3/4	\$ 2.27
1	Service Box	Short 3/4x4 1/2		\$ 1.38
	Old returned	Long 4 1/2x5 1/2		
		Buff. or Rawl.		
9	Ft.	Copper Galv. Iron Pipe at	3/4	\$ 1.67
		Cast Iron		
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt at		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
2	Hrs. Foreman	at		\$ 1.25
4	Hrs. Common Labor	at Tapper		\$ 2.00
4	Hrs. Common Labor	at		\$ 1.80
	Hrs. Mason	at		\$
	Hrs. Masons Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins		16	\$
	Trucking		1	\$
	Builders Use of Water			\$
Total				\$ 14.08

32-20 246 SOUTH 19 32
 Labor and Material Report

246 South St



6 Main Elev. of Main at tap 5
 Gate at 9' to main Gate at
 3/4" copper
 Curb Box

New House
 TAX ID# 309.16.6-13

OK G.M.