

Labor and Materials

1	Lead Connection $\frac{1}{2}$ "	\$
1	Curb Cock $\frac{3}{4}$ "	\$
1	Service Box { Short 3" x 4" Old returned Long 4" x 5" Buffalo	\$
6	Ft. $\frac{3}{4}$ in. G. I. Pipe at	\$
	Nipples..... in. at	\$
	Bushings..... in. at	\$
	Red'g Coup... to... in. at	\$
	Inc'g Coup... to... in. at	\$
	Union... in. at	\$
	Meter... in. at	\$
	Cu. Yds. Br. Stone at	\$
	Cu. Yds. Sand at	\$
	Bags Cement at	\$
	Pav. Brick { Mack Red Asphalt } at	\$
2	Hrs. Foreman at	\$
5	Hrs. Com. Labor at	\$
	Hrs. Mason at	\$
	Hrs. at	\$
	Hrs. at	\$
	Builders' Use of Water	\$
	at	\$
	TRUCK 100	\$
	at	\$
	at	\$
	at	\$
	Total	\$ 10.32

Labor and Material Report

256 SOUTH

May 23

1925

$\frac{1}{2}$ tap at 194 South at (256)

No Measurement

● Curb Box

6 Main

Elev. of Main at tap 4.11

Gate at ●

● Gate at

6' to main

● Curb Box

TAX ID# 309.16-8-13