

### LABOR AND MATERIALS

1	Copper	{ Connection	3/4"	\$	2.27
1	Lead	{			
1	Curb	{ Cock Valve	3/4 in.	\$	2.70
		{ F.S. & V.			
1	Service box	{ Short 3 1/2 x 4 1/2		\$	4.25
	Old returned	{ Long 4 1/2 x 5 1/2			
		{ Buff or Rdway			
10	Ft.	{ Copper		\$	3.50
	3/4 in.	{ G.I.	Pipe at 35		
		{ C.I.			
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g	{ Coupl'gs	to in. at	\$	
	Inc'g	{			
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Compound Joints	at		\$	
	Hrs. Water Maint. Man-1	at		\$	
3	Hrs. Water Maint. Man-2	at 102	\$	306	
	Hrs. Labor	at		\$	
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins. at \$22.26	per C.	\$	07	
	Trucking		\$	1.00	
	Pav't Patch		\$		
	Tap by Moquin		\$		
	O'head		\$		
			\$	16.85	

Tap on Boylston <sup>243</sup> SOUTH

213-7420

St. Pl. Ave. No. 263

South

Name of Owner Mason

Labor and Mat'l. Report Sept 29 19 50

33'2" 21'6"

● Curb Box

Boylston St.

6 Main Elev. of Main at tap 5'

Gate at ● Gate at

10' to main  
3/4" copper

● Curb Box

Tap on Boylston St.

TAX ID# 309.16-10-4

LSM-5C 10-21-49