

Labor and Materials

1	Copper } Connection	\$	
	Lead }	\$	
1	Curb } Cock	\$	
	} Valve	\$	
	} F.S. & V.	\$	
	Service Box } Short 3/4x4 1/2	} <i>old pipe</i>	\$	
	Old returned } Long 4x5 1/2			
		Buff. or Rdway	\$	
7	Ft. } in. } Copper	} Pipe at	\$	
				Galv. Iron
				Cast Iron
	Nipples	in. at	\$	
	Bushings	to in. at	\$	
	Red'g } Couplings	to in. at	\$	
	Inc'g }	\$	
	Union	in. at	\$	
	Meter	in. at	\$	
	Lbs. Br. Stone	at	\$	
	Lbs. Sand	at	\$	
	Bags Cement	at	\$	
	Paving Brick } Mack	} at	\$	
				Red
				Asphalt
	Lead Joints	at	\$	
	Leadite Joints	at	\$	
	Hrs. Foreman	at	\$	
	Hrs. Common Labor	at	\$	
	Hrs. Common Labor	at	\$	
	Hrs. Mason	at	\$	
	Hrs. Mason's Helper	at	\$	
	Hrs. Compressor	at	\$	
	Compensation Ins.		\$	
	Trucking		\$	
	Builders' Use of Water		\$	
	Total	\$		

70 SOUTH

Labor and Material Report *July 19* 19*21*

70 South 210

70

Curb Box

TAX ID# 309.28-2-9

Main Elev of Main at tap

Gate at Gate at

7' to MAIN COPPER

Curb Box