

LABOR AND MATERIALS

_____	Copper	} Connection _____	\$ _____		
_____	Lead				
_____	Curb	} Cock Valve T.S. & V. } _____ in.	\$ _____		
_____				Service box { Short 3-1/2 x 4-1/2 } _____	\$ _____

_____	Ft. _____ in.	{ Copper G.I. C.I. } Pipe at _____	\$ _____		
_____	Nipples _____	in. at _____	\$ _____		
_____	Bushings _____	to _____ in. at _____	\$ _____		
_____	Red'g		\$ _____		
_____	Inc'g		\$ _____		
_____	Union _____	in. at _____	\$ _____		
_____	Meter _____	in. at _____	\$ _____		
_____			\$ _____		
_____	Compound Joints at _____		\$ _____		
_____	Maintenance Foreman _____		\$ _____		
_____	Hrs. Water Maint. Man - 1 at _____		\$ _____		
_____	Hrs. Water Maint. Man - 2 at _____		\$ _____		
_____	Hrs. Garage Foreman _____	at _____	\$ _____		
_____	Hrs. Labor _____	at _____	\$ _____		
_____	Hrs. Compressor at _____		\$ _____		
_____			\$ _____		
_____	Trucking _____		\$ _____		
_____	Pav't Patch _____		\$ _____		
_____			\$ _____		
_____			\$ _____		
_____			\$ _____		
_____			\$ _____		

SOUTH ST St.
Pl. Ave. No. 13

Name of Owner _____
11-17 TAX ID# 300.20-27-4

Labor and Mat'l. Report 102007

4" GATE FOR
SPRINKLER LINE

● Curb Box

6" Main

Elev. of Main at tap 6'10"

Gate at ●

● Gate at

● Curb Box

LABOR AND MATERIALS

_____	Copper } Connection _____	\$ _____
_____	Lead } _____	\$ _____
_____	Curb } Cock } _____ in.	\$ _____
	} Valve } _____	
	} T.S. & V. }	
_____	Service box { Short 3-1/2 x 4-1/2 }	\$ _____
_____	Old returned { Long 4-1/2 x 5-1/2 }	\$ _____
_____	Ft. _____ in. { Copper } Pipe at _____	\$ _____
	} G.I. }	
	} C.I. }	
_____	Nipples _____ in. at _____	\$ _____
_____	Bushings _____ to _____ in. at _____	\$ _____
_____	Red'g _____	\$ _____
_____	Inc'g _____	\$ _____
_____	Union _____ in. at _____	\$ _____
_____	Meter _____ in. at _____	\$ _____
_____	_____	\$ _____
_____	Compound Joints at _____	\$ _____
_____	Maintenance Foreman _____	\$ _____
_____	Hrs. Water Maint. Man - 1 at _____	\$ _____
_____	Hrs. Water Maint. Man - 2 at _____	\$ _____
_____	Hrs. Garage Foreman _____ at _____	\$ _____
_____	Hrs. Labor _____ at _____	\$ _____
_____	Hrs. Compressor at _____	\$ _____
_____	_____	\$ _____
_____	Trucking _____	\$ _____
_____	Pav't Patch _____	\$ _____
_____	_____	\$ _____
_____	_____	\$ _____
_____	_____	\$ _____
_____	_____	\$ _____
_____	_____	\$ _____

St. _____
 Pl. Ave. No. 13

SOUTH ST

Name of Owner _____
11-17? TAX ID # 302.20-27.4

Labor and Mat'l. Report 19 2007

4" Gate For 2" Line

