

Labor and Materials

1	Copper } Connection <i>8 1/2</i>	\$ 2.60
	Lead	
1	Curb } Cock } <i>3/4</i> in.	\$ 7.27
	Valve	
	T.S. & V.	
1	Service Box } Short <i>3/2 x 4 1/2</i>	\$ 1.38
	Old returned } Long <i>4 1/2 x 5 1/2</i>	
		Buff. or Rdway
23	Ft. <i>3/4</i> in. } Copper } Pipe at	\$ 4.14
		Galv. Iron
		Cast Iron
	Nipples..... in. at.....	\$
1	Bushings <i>3/4</i> to <i>1/2</i> in. at.....	\$.10
	Red'g } Couplings..... to..... in. at.....	\$
	Inc'g }	
	Union..... in. at.....	\$
	Meter..... in. at.....	\$
	Lbs. Br. Stone at.....	\$
	Lbs. Sand at.....	\$
	Bags Cement 'at.....	\$
	Paving Brick } Mack } at.....	\$
		Red
		Asphalt
	Lead Joints at.....	\$
	Leadite Joints at.....	\$
5	Hrs. Foreman at.....	\$ 3.13
3	Hrs. Common Labor at..... <i>Tapper</i>	\$ 1.-
1.2	Hrs. Common Labor at.....	\$ 5.40
	Hrs. Mason at.....	\$
	Hrs. Mason's Helper at.....	\$
1 1/2	Hrs. Compressor at.....	\$ 1.50
	Compensation Ins.....	\$.29
	Trucking.....	\$ 1.-
	Builders' Use of Water..... <i>Patch</i>	\$ 23.-
Total \$.		45.81

31-106 **91 SOUTH**

Labor and Material Report *July 18* 19*71*

3/4" Tap 191 South St

TAX ID# 309.28-5-3

10" Main Elev of Main at tap *6.11*

Gate at *23'* to main Gate at

Curb Box

Old tap shut off

Building To be Razed

Shut off at Curb

Oct 2-63 By Larson