

Labor and Materials

1	Copper } Connection.....	2	\$ 2.70
1	Lead } Connection.....	1	\$ 2.39
1	Curb { Cock Valve } in.....	3	\$ 2.39
	{ P. S. & V. }	4	
1	Service Box { Short 3/4x1/2 }		\$ 1.45
	Old returned { Long 1/2x3/4 }		
	{ Buff or Rdway }		
22	20 Ft. 3/4" in. Copper } Pipe at.....	2	\$ 5.40
	Galv. Iron }		
	Cast Iron }		
	Nipples..... in. at.....		\$
	Bushings..... to..... in. at.....		\$
	Red'g } Couplings..... to..... in. at.....		\$
	Inc'g }		\$
	Union..... in. at.....		\$
	Meter..... in. at.....		\$
	Lbs. Br. Stone at.....		\$
	Lbs. Sand at.....		\$
	Bags Cement 'at.....		\$
	Paving Brick { Mack } at.....		\$
	{ Red }		
	{ Asphalt }		
	Lead Joints at.....		\$
	Leadite Joints at.....		\$
5	Hrs. Foreman at.....	3.12	\$ 3.12
14	Hrs. Common Labor at.....	6.30	\$ 6.30
	Hrs. Common Labor at.....		\$
	Hrs. Mason at.....		\$
	Hrs. Mason's Helper at.....		\$
1	Hrs. Compressor at..... 150	1.50	\$ 1.50
	Compensation Ins.....	.29	\$.29
	Trucking.....	1.-	\$ 1.-
	Builders' Use of Water.....	25.-	\$ 25.-
	Total \$	49.15	

30-77 123 South

Labor and Material Report July 10 1930

83 1/2 South Street (123)

10 Main Elev of Main at tap 52

Gate at 22' to main 3/4" COPPER Gate at

● Curb Box

old lead disconnected
Curb box set back
2' - 1962
Shut off at Curb 9/8/73
Curb Box in Sidewalk