

Labor and Materials

1	Copper	Connection	3/4	\$ 2.60
	Lead			
1	Curb	Cock Valve T.S. & V.	3/4 in.	\$ 2.27
1	Service Box	Short 3/4 x 4 1/2		\$ 1.38
	Old returned	Long 4 1/2 x 5 1/2		
		Buff. or Rdway		
32	Ft.	3/4 in.	Copper Galv. Iron Cast Iron	\$ 3.96
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt at		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
5	Hrs. Foreman	at		\$ 3.13
2	Hrs. Common Labor	Tapper		\$ 1.00
17	Hrs. Common Labor	at		\$ 5.40
	Hrs. Mason	at		\$
	Hrs. Mason's Helper	at		\$
1 1/2	Hrs. Compressor	at		\$ 1.50
	Compensation Ins.			\$ 29
	Trucking			\$ 1.00
	Builders' Use of Water	Patch		\$ 23.00
Total \$				45.53

81-12 131 SOUTH 1931

Labor and Material Report

3/4" tap at 131 South st



10' Main Elev of Main at tap 6 1/2'

Gate at ● Gate at ●

3/4" COPPER

● Curb Box

Old taps shut off
Curb box set back
10' - 1962

TAX ID # 309.85-5-6