

Labor and Materials

| | | | | | |
|------------------------|------------|---------------|---------|----|-------|
| Copper | Lead | Connection | 3/4 | \$ | 2.60 |
| Curb | Cock Valve | T-S & V. | in. 3/4 | \$ | 7.30 |
| Service Box | Short | 3/4 x 1 1/2 | | \$ | 1.50 |
| Old returned | Long | 4 1/2 x 5 1/2 | | \$ | |
| | Buff | or Rdway | | \$ | |
| 9 Ft. | Copper | Pipe at | 3/4 | \$ | 1.86 |
| X | Cast Iron | | | \$ | |
| Nipples | | in. at | | \$ | |
| Bushings | | to in. at | | \$ | |
| Red'g | Couplings | to in. at | | \$ | |
| Inc'g | | | | \$ | |
| Union | | in. at | | \$ | |
| Meter | | in. at | | \$ | |
| Lbs. Br. Stone | | at | | \$ | |
| Lbs. Sand | | at | | \$ | |
| Bags Cement | | at | | \$ | |
| Paving Brick | Mack | at | | \$ | |
| | Red | | | \$ | |
| | Asphalt | | | \$ | |
| Lead Joints | | at | | \$ | |
| Leadite Joints | | at | | \$ | |
| 3 Hrs. Foreman | | at | | \$ | 1.55 |
| 1.7 Hrs. Common Labor | | at | | \$ | 4.78 |
| Hrs. Common Labor | | at | | \$ | |
| Hrs. Mason | | at | | \$ | |
| Hrs. Mason's Helper | | at | | \$ | |
| 2 Hrs. Compressor | | at | | \$ | 3.00 |
| Compensation Ins. | | | | \$ | 23 |
| Trucking | | | | \$ | 1.00 |
| Builders' Use of Water | | Patch | | \$ | 25.00 |

Total \$44.25

74-123-140 SOUTH
 Labor and Material Report Aug 12 1929
 96-96 1/2 South St (140)

23' 5" 23' 10" Curb Box

10 Main Elev of Main at tap 6

Gate at 9' to MAIN 3/4" COPPER Gate at

Curb Box

old Tap 18 Bc dug up
 Curb box set back
 2' - 1962
 TAX ID# 309.36-2-19