

Labor and Materials

1	Copper } Connection <i>3/4</i>	\$ 2.60
	Lead	
1	Curb } Cock Valve T-S-&V. } <i>3/4</i> in.	\$ 2.27
1	Service Box } Short <i>3/4x1 1/2</i>	\$ 1.38
	Old returned } Long <i>1 1/2x2 1/2</i>	
22	Pt. <i>3/4</i> in. } Copper Galv. Iron } Pipe at	\$ 3.96
	Nipples.....in. at.....	\$
	Bushings.....to.....in. at.....	\$
	Red'g } Couplings.....to.....in. at.....	\$
	Inc'g }	
	Union.....in. at.....	\$
	Meter.....in. at.....	\$
	Lbs. Br. Stone at.....	\$
	Lbs. Sand at.....	\$
	Bags Cement 'at.....	\$
	Paving Brick } Mack } at	\$
	Asphalt }	
	Lead Joints at.....	\$
	Leadite Joints at.....	\$
5	Hrs. Foreman at.....	\$ 3.13
2	Hrs. Common Labor Tapper.....	\$ 1.00
12	Hrs. Common Labor at.....	\$ 5.40
	Hrs Mason at.....	\$
	Hrs Mason's Helper at.....	\$
1 1/2	Hrs. Compressor at.....	\$ 1.50
	Compensation Ins.....	\$.29
	Trucking.....	\$ 1.00
	Builders' Use of Water <i>Patch</i>	\$ 23.00
	Total \$	45.63

31-131 **141 SOUTH** 1957

Labor and Material Report

141

10' Main

Elev of Main at tap *6*

Gate at ●

22' *3/4*" COPPER

● Curb Box

Old tap shut off

TAX ID # 309.35-5-1