

### Labor and Materials

2	Copper } Connection		\$ 3.20
	Lead } .....		
3	Curb { Cock	1 in.	\$ 1.00
	Valve } .....		
	T. S. & V. } .....		
1	Service Box { Short 3 1/2 x 4 1/2	}	\$ 1.40
	Old returned { Long 4 1/2 x 5 1/2		
	Buff. or Rdway } .....		
25	Ft. .... in. { Copper	} Pipe at	\$ 5.50
	Galv. Iron } .....		
	Cast Iron } .....		
	Nipples. .... in. at		\$
	Bushings. .... to .... in. at		\$
	Red'g } Couplings. .... to .... in. at		\$
	Inc'g } .....		\$
	Union. .... in. at		\$
	Meter. .... in. at		\$
	Lbs. Br. Stone at		\$
	Lbs. Sand at		\$
	Bags Cement at		\$
	Paving Brick { Mack	} at	\$
	Red } .....		
	Asphalt } .....		
	Lead Joints at		\$
	Leadite Joints at		\$
6	Hrs. Foreman at	6 2/5	\$ 1.88
12	Hrs. Common Labor at	50	\$ 6.00
11	Hrs. Common Labor at	4 2/8	\$ 4.46
	Hrs. Mason at		\$
	Hrs. Mason's Helper at		\$
1	Hrs. Compressor at	2.00	\$ 2.00
	Compensation Ins.		\$ .38
	Trucking		\$ 1.00
	Builders' Use of Water		\$
Total			\$ 26.82

### Labor and Material Report

19

149 SOUTH

76-30



6 1/2 Main

Elev. of Main at tap 5.44

Gate at

Gate at

25' to MAIN  
3/4" Copper

Curb Box

TAX ID# 309.12-2-1