

Labor and Materials

1	Copper } Connection		\$ 3.20
	Lead }		
1	Curb } Cock	1" in.	\$ 1.00
	Valve }		
	T. S. & V. }		
1	Service Box } Short 3 1/2 x 4		\$ 1.30
	Old returned } Long 4 1/2 x 5		
		Buff. or Rdway	
10	Ft. 1 in. } Copper	Pipe at	\$ 2.20
		Galv. Iron	
		Cast Iron	
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g } Couplings	to in. at	\$
	Inc'g }		
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone	at	\$
	Lbs. Sand	at	\$
	Bags Cement	at	\$
	Paving Brick } Mack	at	\$
		Red	
		Asphalt	
	Lead Joints	at	\$
	Leadite Joints	at	\$
3	Hrs. Foreman	at	\$ 1.58
7	Hrs. Common Labor	at	\$ 2.84
	Hrs. Common Labor	at	\$
	Hrs. Mason	at	\$
	Hrs. Mason's Helper	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins.	at	\$ 1.2
	Trucking	at	\$ 1.00
	Builders' Use of Water	at	\$
Total			\$ 13.54

155 SOUTH

Labor and Material Report Nov. 19 24

111 South St (155)

SOUTH ST

TAP ON FIRST

SEWER GOES TO 1ST ST. Elev. of Main at tap

Gate at ● ● Gate at

10' to main

1" GAB

● Curb Box

Old tap to be dug up on south

TAX ID # 309.12-9-8