Labor and Materials

1	~~Lead~~ Connection 3/4	$
1	Curb Cock 3/4	$
1	Service Box Old returned { Short 3½ x 4½ / Long 4½ x 5½ / Buffalo	$
21	Ft. 3/4 in. G. I. Pipe at Copper	$
	Nipples ... in. at	$
1	Bushings 3/4 to 1/2 in. at	$
	Red'g Coup ... to ... in. at	$
1	~~Inc'g~~ Coup ... to ... in. at Brass	$
	Union ... in. at	$
	Meter ... in. at	$
	Cu. Yds. Br. Stone at	$
	Cu. Yds. Sand at	$
	Bags Cement at	$
	Paving Brick { Mack / Red / Asphalt } at	$
4	Hrs. Foreman at	$
21	Hrs. Common Labor at	$
	Hrs. Mason at	$
7	Hrs. Compressor at	$ 3.00
	Hrs. at	$
800	Builders' Use of Water	$
	at	$
	Truck 100 at	$
	at	$
	Payment at	$
	Total	$ 24.37

161 SOUTH

Labor and Material Report Oct 20 19 [illegible]

3/4 [illegible] at ~~117~~ 161 South at

6 Main

Elev. of Main at tap [illegible]

Gate at ● ● Gate at

21' to MAIN
3/4" COPPER

● Curb Box

Payment

TAX ID # 309.12-9-5