

### Labor and Materials

1 m	Copper } Connection.....	\$.....
	Lead } .....	\$.....
1	Curb } Cock } 1 in.....	\$.....
	Valve } T. S. & V. } .....	\$.....
	Service Box } Short 3½ x 4½ } .....	\$.....
	Old returned } Long 4½ x 5½ } .....	\$.....
		Buff. or Rdway } .....
8	Ft. } in. } Copper } Pipe at.....	\$.....
		Galv. Iron } .....
		Cast Iron } .....
	Nipples..... in. at.....	\$.....
	Bushings..... to..... in. at.....	\$.....
	Red'g } Couplings..... to..... in. at.....	\$.....
	Inc'g } .....	\$.....
	Union..... in. at.....	\$.....
	Meter..... in. at.....	\$.....
	Lbs Br. Stone at.....	\$.....
	Lbs. Sand at.....	\$.....
	Bags Cement at.....	\$.....
	Paving Brick } Mack } at.....	\$.....
		Red } .....
		Asphalt } .....
	Lead Joints at.....	\$.....
	Leadite Joints at.....	\$.....
	Hrs. Foreman at.....	\$.....
	Hrs. Common Labor at.....	\$.....
	Hrs. Common Labor at.....	\$.....
	Hrs. Mason at.....	\$.....
	Hrs. Mason's Helper at.....	\$.....
	Hrs. Compressor at.....	\$.....
	Compensation Ins.....	\$.....
	Trucking.....	\$.....
	Builders' Use of Water.....	\$.....

Total \$.....

22 South St.

Labor and Material Report 191

Hotel Madison South St

● Curb Box

Main	Elev. of Main at tap
Gate at ●	● Gate at
8' to main	

● Curb Box

1" Tap.

HAS GATE COVER  
ON IT