

Labor and Materials

Copper	}	Connection.....	\$	
Lead					
Curb	}	Cock Valve T. S. & V. in	\$	
Service Box					
Old returned					
	}	Short 3½ x 4½	\$	
		Long 4½ x 5½			
		Buff. or Rdway			
Ft.	}	Copper	Pipe at	\$	
in.		Cast Iron			
		Cast Iron			
Nipples	in. at			\$	
Bushings	to	in. at		\$	
Red'g	}	Conplings.....	to	in. at	\$
Inc'g					
Union	in. at			\$	
Meter	in. at			\$	
Lead Joints at				\$	
Leadite Joints at				\$	
Hrs. Foreman at				\$	
Hrs. Chauffeur at				\$	
Hrs. Tapper at				\$	
Hrs. Labor at				\$	
Hrs. Labor at				\$	
Hrs. Compressor at				\$	
Compensation Ins.				\$	
Trucking				\$	
Builders Use of Water				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	

174 SOUTH

St. _____
Pt. _____
Ave. No. 174

Name of Owner _____

Labor and Mat'l. Report 10-19-1921

39-0 35-8

● Curb Box

TAX ID# 309.12-11-33

.....Main Elev. of
Main at tap.....

Gate at ● ● Gate at

● Curb Box