

**Labor and Materials**

Copper	Connection		\$ 3.20
Lead			
Curb	Cock Valve T. S. & V.	in.	\$ 1.00
Service Box	Short $3\frac{1}{2} \times 1\frac{1}{2}$		\$ 1.30
Old returned	Buff or Railway		
10 Ft.	Copper	Pipe at	\$ 2.20
	Cast Iron		
Nipples	in. at		\$
Bushings	to in. at		\$
Red'g Inc'g	Couplings	to in. at	\$
Union	in. at		\$
Meter	in. at		\$
Lbs. Br. Stone	at		\$
Lbs. Sand	at		\$
Bags Cement	at		\$
Paving Brick	Mack Red Asphalt	at	\$
Lead Joints	at		\$
Leadite Joints	at		\$
Hrs. Foreman	at		\$
3 Hrs	Common Labor	at	\$ 1.50
11 Hrs	Common Labor	at	\$ 4.47
Hrs	Mason	at	\$
Hrs	Mason's Helper	at	\$
Hrs	Compressor	at	\$
Compensation	Ins		\$ 1.6
Trucking			\$ 1.00
Builders' Use of Water			\$
Total \$			14.83

183 SOUTH

Labor and Material Report *Sept 18 1928*

~~133~~ South St (183)

39' 38' 11'

Curb Box

Third St

South St

---

4 Main Elev of Main at tap 4 1/2

Gate at 10' to main 3/4" copper Gate at

Curb Box

TAX ID # 309.12-10-1