

751

Labor and Materials

Copper } Connection.....	1	\$ 1.48
Lead }		
Curb { Cock }	1	\$ 1.79
{ Valve }		
{ T.S.&V. }		
1. Service Box { Short 3 1/2 x 4 1/2 }	1	\$ 1.30
Old returned { Long 4 1/2 x 5 1/2 }		
{ Buff on Rdway }		
13' 8" Ft. in. { Copper } Pipe at 3	3	\$ 1.44
{ Galv. Iron }		
{ Cast Iron }		
..... Nipples in. at		\$
..... Bushings to in. at		\$
..... Red'g } Couplings..... to..... in. at.....		\$
..... Inc'g }		
..... Union..... in. at		\$
..... Meter..... in. at		\$
..... Lbs. Br. Stone at		\$
..... Lbs. Sand at		\$
..... Bags Cement at		\$
..... Paving Brick { Mack } at		\$
{ Red }		
{ Asphalt }		
..... Lead Joints at		\$
..... Leadite Joints at		\$
3. Hrs. Foreman at	1.88	\$ 1.88
4. Hrs. Common Labor at <i>Tappers</i>	2.52	\$ 2.52
5. Hrs. Common Labor at		\$
..... Hrs. Mason at		\$
..... Hrs. Masons Helper at		\$
..... Hrs. Compressor at		\$
..... Compensation Ins	19	\$ 19
..... Trucking	1	\$ 1
..... Builders Use of Water <i>Patch</i>	5	\$ 5
Total \$		18.23

32-51 May 20 1932

Labor and Material Report

186 South St.

6" Main 1995 Elev. of Main at tap *74*

Gate at 13' 8" to main Gate at

3/4" copper

● Curb Box

old Tap to be dug up

TAX ID # 309.12-11-41

OK *9/10*