

Labor and Materials

1	Copper } Connection. ³⁴	\$ 320
	Lead }	
1 1/2	Curb } Cock }	\$ 100
	Valve } T.S. & V. }	
1	Service Box } Short 3" x 4" }	\$ 130
	Old returned } Long 4" x 5" }	
		Buff. or Rdway }
23	3/4 in. } Copper } Pipe at.	\$ 506
		Galv. Iron }
		Cast Iron }
	Nipples.....in. at.....	\$
	Bushings.....to.....in. at.....	\$
1	Red } Couplings. ³⁴ to.....in. at.....	\$ 15
	Inc'g }	
	Union.....in. at.....	\$
	Meter.....in. at.....	\$
	Lbs. Br. Stone at.....	\$
	Lbs. Sand at.....	\$
	Bags Cement at.....	\$
	Paving Brick } Mack } at.....	\$
		Red }
		Asphalt }
	Lead Joints at.....	\$
	Leadite Joints at.....	\$
31	Hrs. Foreman at..... ^{62.5}	\$ 1938
	Hrs. Common Labor at.....	\$
32	Hrs. Common Labor at..... ^{40.8}	\$ 1300
	Hrs. Mason at.....	\$
	Hrs. Mason's Helper at.....	\$
	Hrs. Compressor at.....	\$
	Compensation Ins.....	\$ 85
1	Trucking.....	\$ 150
	Builders' Use of Water.....	\$
	Total	\$ 4494

27-67 193 SOUTH 4

Labor and Material Report

1927



6 in Main Elev. of Main at tap. 4

Gate at 23' to MAIN 3/4" COPPER Gate at

Curb Box

old tap Disconnected

TAX ID # 309.12-13-2