

## LABOR AND MATERIALS

1	Copper Lead	} Connection	3/4		\$ 1.35
1	Curb	{ Cock Valve F. S. & V.	3/4 in.		\$ 1.80
1	Service Box Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buffer Rdway			\$ 1.82
9	Ft.	{ Copper Galv Iron Cast Iron	3/4 in.	Tube/ops Pipe at 18'	\$ 1.62
	Nipples		..... in. at		\$
	Bushings		..... to ..... in. at		\$
	Red'g Inc'g	} Couplings	..... to ..... in. at		\$
	Union		..... in. at		\$
	Meter		..... in. at		\$
2	Lead Joints at	Lead to Iron Conn.			\$ 30
	Leadite Joints at				\$
	Hrs. Foreman at				\$
	Hrs. Chauffeur at				\$
10	Hrs. Tapper at	6.8314			\$ 6.88
	Hrs. Labor at				\$
	Hrs. Labor at				\$
	Hrs. Compressor at				\$
	Compensation Ins.	2.2.13			\$ 15
	Trucking				\$ 1.72
	Builders Use of Water				\$ 5.85
	Tap by Hessel				\$
					\$
					\$
					\$
					\$
					\$
					\$ 20.77

St. Spring St  
 Pl. 7  
 Ave. No. 7

Name of Owner Dexter

---

Labor and Mat'l. Report June 10 1943

360°

28'6"

● Curb Box

---

4 Main Elev. of  
Main at tap 6

Gate at ● ● Gate at

9' to main

---

● Curb Box

Shut off at Curb  
3-5-73