

Labor and Materials

1	Copper	Connection	3/4"	\$	
	Lead				
1	Curb	Cock Valve	3/4" in.	\$	
		T. S. & V.			
1	Service Box	Short	3/4" x 4 1/2"	\$	
	Old returned	Long	4 1/2" x 5 1/2"		
		Buff. or Rdway			
7	Ft.	3/4" in.	Copper	Pipe at	\$
			Galv. Iron		
			Cast Iron		
	Nipples			in. at	\$
	Bushings			to in. at	\$
	Red'g	Couplings		to in. at	\$
	Inc'g				
	Union			in. at	\$
	Meter			in. at	\$
	Lbs. Br. Stone			at	\$
	Lbs. Sand			at	\$
	Bags Cement			'at	\$
	Paving Brick	Mack		'at	\$
		Red			
		Asphalt			
	Lead Joints			at	\$
	Leadite Joints			at	\$
	Hrs. Foreman			at	\$
	Hrs. Common Labor			at	\$
	Hrs. Common Labor			at	\$
	Hrs. Mason			at	\$
	Hrs. Mason's Helper			at	\$
	Hrs. Compressor			at	\$
	Compensation Ins				\$
	Trucking				\$
	Builders' Use of Water				\$
	Total \$				\$

Labor and Material Report Aug 25 19 28

3/4" tap on staple at lot 17 east side
staple slope
manhole
going south

See below
↓

#17-TAX ID# 309.11-5-8

6" Main Elev of Main at tap 4.4

Gate at 7' to MAIN ● Gate at

● Curb Box

Measurement from 63'