

21

Labor and Material Report July 11 1948

no 19 Staple at

Curb Box

6" Main Elev. of Main at tap 8'

Gate at ● ● Gate at

● Curb Box

21

Labor and Material Report Aug 24 1948

194 21 Staple at

Curb Box

6" Main Elev. of Main at tap 24'

Gate at ● ● Gate at

24' to MAIN

3/4" copper ● Curb Box

Morris Franston
Est

TAX ID# 309.11-5-7

Labor and Materials

1	Lead Connection	\$
1	Curb Cock	\$
1	Service Box { Short 3 $\frac{1}{2}$ x 4 $\frac{1}{2}$ Old returned { Long 4 $\frac{1}{2}$ x 6 $\frac{1}{2}$ Buffalo	\$
20	Ft. $\frac{3}{4}$ in. G.I. Pipe at	\$
	Nipples..... in. at	\$
1	Bushings $\frac{1}{2}$ to $\frac{3}{4}$ in. at	\$
	Red'g Coup..... to..... in. at	\$
	Inc'g Coup..... to..... in. at	\$
	Union..... in. at	\$
	Meter..... in. at	\$
	Cu. Yds. Br. Stone at	\$
	Cu. Yds. Sand at	\$
	Bags Cement at	\$
	Paving Brick { Mack Red Asphalt } at	\$
	Hrs. Foreman at	\$
	Hrs. Common Labor at	\$
	Hrs. Mason at	\$
	Hrs..... at	\$
	Hrs..... at	\$
	Builders' Use of Water	\$
 at	\$
 at	\$
 at	\$
 at	\$
 at	\$
 at	\$
 at	\$
	Total	\$	

Labor and Materials

1	Copper } Connection $\frac{3}{4}$ Leat	\$
1	Curb { Cock Valve } $\frac{3}{4}$ in.....	\$
1	Service Box { Short 3 $\frac{1}{2}$ x 4 $\frac{1}{2}$ Old returned { Long 4 $\frac{1}{2}$ x 5 $\frac{1}{2}$ Buff. or Rdway }	\$
24	Ft. $\frac{3}{4}$ in. } Copper Galv. Iron } Pipe at	\$
	Nipples..... in. at	\$
1	Bushings $\frac{3}{4}$ to $\frac{1}{2}$ in. at	\$
	Red'g } Couplings..... to..... in. at	\$
	Inc'g }		
	Union..... in. at	\$
	Meter..... in. at	\$
	Lbs. Br. Stone at	\$
	Lbs. Sand at	\$
	Bags Cement at	\$
	Paving Brick { Mack Red Asphalt } at	\$
	Lead Joints at	\$
	Leadite Joints at	\$
	Hrs. Foreman at	\$
	Hrs. Common Labor at	\$
	Hrs. Common Labor at	\$
	Hrs Mason at	\$
	Hrs Mason's Helper at	\$
	Hrs. Compressor at	\$
	Compensation Ins	\$
	Trucking	\$
	Builders' Use of Water	\$
	Total	\$	

Labor and Materials

1	Copper Lead	Connection	$\frac{3}{4}$ "	\$ 3.20
1	Curb	Cock Valve F.S. & V.	$\frac{3}{4}$ " in.	\$ 1.00
1	Service Box Old returned	Short $3\frac{1}{2}$ x $4\frac{1}{2}$ Long $4\frac{1}{2}$ x $5\frac{1}{2}$ Buff. or Rdway		\$ 1.30
20	Ft. $\frac{3}{4}$ " in.	Copper Galv. Iron Cast Iron	Pipe at	\$ 4.00
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs Br. Stone	at		\$
	Lbs Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	(Mack Red Asphalt)	at	\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
2	Hrs. Foreman	at	62.15	\$ 1.25
5	Hrs. Common Labor	at	50	\$ 2.50
5	Hrs. Common Labor	at	40 $\frac{1}{8}$	\$ 2.03
	Hrs. Mason	at		\$
	Hrs. Mason's Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.			\$ 1.00
	Trucking			\$ 1.00
	Builders' Use of Water			\$
Total				\$ 16.84

Labor and Material Report

6 - 18 1926

Vacant Lot
Tap South end at
Staple + Third St

● Curb Box

6 Main

Elev. of
Main at tap 4'

Gate at ●
20' to MAIN

● Gate at

● Curb Box

New Tap
Vaughan