

52
Labor and Material Report

Aug 20

1928

3/4 tap for lot No 11

Measurement
for lot No 11



→
going south

● Curb Box

6" Main

Elev of
Main at tap

4.1

Gate at ●

● Gate at

● Curb Box

Frank Thomas

52
Labor and Material Report

Aug 20

1928

3/4 tap at 58 stable st



● Curb Box

6" Main

Elev of
Main at tap

4.1

Gate at ●

● Gate at

6' to MAIN

3/4" copper

● Curb Box

Glen Norton

TAX ID # 309.11-13-12

Labor and Materials

1	Copper Lead	Connection	3/4	\$
1	Curb	Cock Valve T. S. & V.	in.	\$
1	Service Box Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway		\$
24	Pt. 3/4	Copper Galv. Iron Cast Iron	Pipe at	\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt	at	\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
	Hrs. Foreman	at		\$
	Hrs. Common Labor	at		\$
	Hrs. Common Labor	at		\$
	Hrs. Mason	at		\$
	Hrs. Mason's Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins			\$
	Trucking			\$
	Builders' Use of Water			\$
	Total \$			\$

Labor and Materials

1	Copper Lead	Connection		\$
1	Curb	Cock Valve T. S. & V.	3/4 in.	\$
1	Service Box Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway		\$
6	Pt. 3/4	Copper Galv. Iron Cast Iron	Pipe at	\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt	at	\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
	Hrs. Foreman	at		\$
	Hrs. Common Labor	at		\$
	Hrs. Common Labor	at		\$
	Hrs. Mason	at		\$
	Hrs. Mason's Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins			\$
	Trucking			\$
	Builders' Use of Water			\$
	Total \$			\$