

Labor and Materials

✓ 1. Lead Connection	\$.....
✓ 1. Curb Cock	\$.....
1 Service Box { Short 3 1/2 x 4 1/2 Old returned { Long 4 1/2 x 5 1/2 Buffalo	\$.....
20 Ft. 3/4 in. G.I. Pipe at.....	\$.....
Nipples in. at.....	\$.....
Bushings to..... in. at.....	\$.....
Red'g Coup.... to..... in. at.....	\$.....
Ine'g Coup.... to..... in. at.....	\$.....
Union..... in. at.....	\$.....
Meter..... in. at.....	\$.....
Cu. Yds. Br. Stone at.....	\$.....
Cu. Yds. Sand at.....	\$.....
Bags Cement at.....	\$.....
Paving Brick { Mack Red Asphalt } at.....	\$.....
Hrs. Foreman at	\$.....
Hrs. Common Labor at	\$.....
Hrs. Mason at	\$.....
Hrs. at	\$.....
Hrs. at	\$.....
Builders' Use of Water	\$.....
..... at	\$.....
..... at	\$.....
..... at	\$.....
..... at	\$.....
Total \$.....	

Labor and Material Report July 11 1919

No 55 Slope 25

6" Main

Elev. of Main at tap

Gate at ●

20' to main

● Gate at

● Curb Box

measuring box
56 Slope