

**Labor and Materials**

Lead Connection.....	\$.....
Curb Cock.....	\$.....
Service Box (Short 8 1/2 x 4 1/2 Old returned Long 4 1/2 x 5 1/2 Buffalo.....)	\$.....
20 Ft. 3/4" in. Copper Pipe at.....	\$.....
Nipples..... in. at.....	\$.....
Bushings..... to..... in. at.....	\$.....
Red'g Coup..... to..... in. at.....	\$.....
Inc'g Coup..... to..... in. at.....	\$.....
Union..... in. at.....	\$.....
Meter..... in. at.....	\$.....
Cu. Yds. Br. Stone at.....	\$.....
Cu. Yds. Sand at.....	\$.....
Bags Cement at.....	\$.....
Paving Brick { Mack Red } at.....	\$.....
Asphalt } .....	\$.....
Hrs. Foreman at.....	\$.....
Hrs. Common Labor at.....	\$.....
Hrs. Mason at.....	\$.....
Hrs..... at.....	\$.....
Hrs..... at.....	\$.....
Builders' Use of Water.....	\$.....
..... at.....	\$.....
..... at.....	\$.....
..... at.....	\$.....
..... at.....	\$.....
Total \$.....	\$.....

**Labor and Material Report** July 11 1928

No 69 Staple st SW corner

28'0" Curb Box 34'2"

Fifth St.

6' Main Tap ON 5th St. Elev. of Main at tap 6'

Gate at 20' to main 133' 6" Gate at

3/4" COPPER

Curb Box

Tax ID# 309.11-14-8

Note - curb stop leaks in opp. pos.