

LABOR AND MATERIALS

1	Copper Lead	Connection	<u>3/4"</u>	\$	
1	Curb	Cock Valve T.S. & V.	} <u>3/4" in.</u>	\$	
1	Service box Old returned	Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff. or Rdway.	}	\$	
17	² / ₂ Ft. <u>3/4</u> in.	Copper G.I. C.I.	} Pipe at	\$	
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	Coupl'gs. to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Compound Joints	at		\$	
	Maintenance Foreman			\$	
	Hrs. Water Maint. Man	—1 at		\$	
	Hrs. Water Maint. Man	—2 at		\$	
	Hrs. Garage Foreman	at		\$	
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins.	at \$ per C		\$	
	Trucking			\$	
	Pav't Patch			\$	
	<i>Measured in Jan. 1971</i>			\$	
	<i>by Larcant & Co.</i>			\$	
	O'head			\$	

St. Staple
~~Pl.~~
 Ave. No. 80

Name of Owner P. Caranagh

Labor and Mat'l. Report June 30 1978

6' Main Elev. of Main at tap 4'

Gate at • • Gate at

TAX ID # 309.15-3-12

Was Lot Tap. • Curb Box
New House 1970-71.
3/4" copper
17' to MAIN

LSM-5C-6-1-67