

Labor and Material Report Aug 24 1928

3/4 tap for House in lot west side



6" Main *Staple St* Elev of Main at tap *4 ft*
 Gate at ● Gate at ●

● Curb Box

Labor and Material Report Aug 25 1928

3/4 tap for house staple st



6" Main Elev of Main at tap *4 ft*
 Gate at ● Gate at ●
7' to main

● Curb Box

Lot 63
 Kattonbach
 Chestertown

Labor and Materials

1	Copper } Connection $3/4$	\$
	Lead	
1	Curb } Cock Valve } $3/4$ in.	\$
	T.S. & V.	
1	Service Box } Short $3/4 \times 4 1/2$	\$
	Old returned } Long $4 1/2 \times 5 1/2$	
	Buff. or Rdway }	
22	Pt. $3/4$ in. } Copper Galv. Iron } Pipe at	\$
	Nipples..... in. at	\$
	Bushings..... to..... in. at	\$
	Red'g } Couplings..... to..... in. at	\$
	Inc'g }	
	Union..... in. at	\$
	Meter..... in. at	\$
	Lbs. Br. Stone at	\$
	Lbs. Sand at	\$
	Bags Cement 'at	\$
	Paving Brick } Mack } at	\$
	Lead Joints at	\$
	Leadite Joints at	\$
	Hrs. Foreman at	\$
	Hrs. Common Labor at	\$
	Hrs. Mason at	\$
	Hrs. Mason's Helper at	\$
	Hrs. Compressor at	\$
	Compensation Ins	\$
	Trucking	\$
	Builders' Use of Water	\$
	<u>Total \$</u>	

Labor and Materials

1	Copper } Connection $3/4$	\$
	Lead	
1	Curb } Cock Valve } $3/4$ in.	\$
	T.S. & V.	
1	Service Box } Short $3/4 \times 4 1/2$	\$
	Old returned } Long $4 1/2 \times 5 1/2$	
	Buff. or Rdway }	
7	Pt. $3/4$ in. } Copper Galv. Iron } Pipe at	\$
	Nipples..... in. at	\$
	Bushings..... to..... in. at	\$
	Red'g } Couplings..... to..... in. at	\$
	Inc'g }	
	Union..... in. at	\$
	Meter..... in. at	\$
	Lbs. Br. Stone at	\$
	Lbs. Sand at	\$
	Bags Cement 'at	\$
	Paving Brick } Mack } at	\$
	Lead Joints at	\$
	Leadite Joints at	\$
	Hrs. Foreman at	\$
	Hrs. Common Labor at	\$
	Hrs. Mason at	\$
	Hrs. Mason's Helper at	\$
	Hrs. Compressor at	\$
	Compensation Ins	\$
	Trucking	\$
	Builders' Use of Water	\$
	<u>Total \$</u>	