

Labor and Material Report *Aug 24* 1928

Vacant lot west side  
manhole

38.8

56.7"

68' is set at

Curb Box

---

6" Main

Elev of Main at tap *4/11*

Gate at ● Gate at ●

---

Lot No 14 ● Curb Box

*James M. Derry*

Labor and Material Report *Aug 24* 1928

3/4 tap at 14 Staple at

14

20.3"

19.10"

14  
Staple at

Curb Box

---

6" Main

Elev of Main at tap *4/11*

Gate at ● Gate at ●

---

● Curb Box

*Mrs S. WIGGINS*

TAX ID# 309.11-7-17

### Labor and Materials

1	Copper Lead	Connection	3/4	\$
1	Curb	Cock Valve T-S-&V.	3/4 in.	\$
1	Service Box Old returned	Short 3/4x1 1/2 Long 1 1/2x3 1/2 Buff. or Rdway		\$
24	Ft.	3/4 in.	Copper Galv. Iron Cast Iron	Pipe at \$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt	at	\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
	Hrs. Foreman	at		\$
	Hrs. Common Labor	at		\$
	Hrs. Common Labor	at		\$
	Hrs. Mason	at		\$
	Hrs. Mason's Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins			\$
	Trucking			\$
	Builders' Use of Water			\$
	Total \$			\$

### Labor and Materials

1	Copper Lead	Connection	3/4	\$
1	Curb	Cock Valve T-S-&V.	3/4 in.	\$
1	Service Box Old returned	Short 3/4x1 1/2 Long 1 1/2x3 1/2 Buff. or Rdway		\$
7	Ft.	3/4 in.	Copper Galv. Iron Cast Iron	Pipe at \$
	Nipples	in. at		\$
1	Bushings	3/4 to 1/2 in. at		\$
	Red'g Inc'g	Couplings	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt	at	\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
	Hrs. Foreman	at		\$
	Hrs. Common Labor	at		\$
	Hrs. Common Labor	at		\$
	Hrs. Mason	at		\$
	Hrs. Mason's Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins			\$
	Trucking			\$
	Builders' Use of Water			\$
	Total \$			\$

